



Please note that NNTN8294 and NNTN8295 are not FM approved.



Favor notar que NNTN8294 e NNTN8295 não são aprovados pelo FM.



請注意，NNTN8294 及 NNTN8295 未經 FM 認證。



請注意，NNTN8294 和 NNTN8295 未經 FM 認證。



NNTN8294 및 NNTN8295 는 FM 승인을 받은 품목이 아닙니다 .



Bitte beachten Sie, dass NNTN8294 und NNTN8295 nicht FM-zugelassen sind.



Veillez noter que le NNTN8294 et le NNTN8295 ne sont pas approuvés FM.



Precaución

Tenga en cuenta que NNTN8294 y NNTN8295 no están aprobados para FM.



Attenzione

Tenere presente che NNTN8294 e NNTN8295 non sono approvati per l'FM.



Voorzichtig

Let op: NNTN8294 en NNTN8295 zijn niet goedgekeurd voor FM.



Осторожно!

Пожалуйста, обратите внимание, что модели NNTN8294 и NNTN8295, не поддерживают работу в FM-диапазоне.

MOTOROLA, MOTO, MOTOROLA SOLUTIONS and the Stylized M logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners.

© 2012 Motorola Solutions, Inc.

All rights reserved.



68012006079-A

2

